25X1

IB - 289/63 29 October 1963 Copy / of /

MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR

ATTENTION

Chief, Requirements Branch, Reconnaissance Group, CGS

THROUGH FROM

: Chief, CIA/PID (NPIC)

SUBJECT

X1

Rail Facilities at Tien-ching (Tientsin), China

REFERENCE

- (1) ORR Requirement No. C-RR3-80,539
- (2) CIA/PID Project No. C 1246/63
- 1. This memorandum is in answer to the referenced requirement concerning the comparative study of the rail and repair facilities at Tien-ching (Tientsin), China. This is the second and final part of the study covering this complex.
- 2. The enclosed information provides the location of rail facilities, including rail-served industries. Two tables have been provided, one showing the 25X1 length and the width of each yard of a given area, and the other reporting the number and type of rolling stock found in each yard or rail-served industry. information was derived from [respectively. Information was also obtained from US Air Target

Mosaic #50381-6/4MA.

- 3. On the enclosed map of Tien-ching (Tientsin) (CIA/PID/IB-P-641/63, Enclosure No. 1), the numbered annotations correspond to the facility areas listed in the attached tables, (Tables I and II). The letters which divide the enumerated areas correspond to yards and the rail-served industries. It should be noted that all of the rail-served industries could not be identified.
- 4. Included with this memorandum is a diagrammatic sketch of the locomotive repair facility (Enclosure No. 2) located in area 1. All necessary information is annotated on this sketch.
- 5. The locomotive and car repair facility located in area 3 was not operational at the time of photography. This installation includes a roundhouse (12 stalls approx.), two car repair shops, foundry, machine shop and thirteen support buildings.
- 6. The turntable that services the moundhouse, of the aforementioned facility, is not operational and is partly obscured by a building that has been constructed on the service tracks. Two turning wyes are located adjacent to this facility.

Declass Review by NGA

UL 3112

25X1

1147

•	SECRET	25)
. •	SUBJECT: Rail Facilities at Tien-Ching (Tientsin), China	
	The turning wyes are operational and have useable tracks of and 460 feet (approx.).	25)
·V4	7. These requirements are considered to be completed as of the date of this memorandum. The photo analysis on this project was performed by Messrs.	
X1	you have further questions regarding this project.	25) -
	ENCLOSURES: 1 Line Drawing (CIA/PID/IB-P-642/63) 1 Mosaic (CIA/PID/IB-P-641/63) 2 Tables	
	SECRET	25

1	051
大·利益銀行管	25X
VLUIL	

TABLE I

RAIL FACILITIES: LENGTE AND WIDTH BY YARDS

TIEN-CHING (TIENTSIN), CHINA

25X1

RAIL FACILITY	YARD	LENGTH (FEET) *(-)	WIDTH (NO. OF TRACKS)
1	A	1525 75'	12
1	В	1500' x 1400'	26
	c	2500' x 250'	9
	D	1500' x 30'	12
	E	1000' x 150'	11
	D E F G		1 -0
	G	4000' x 300'	18
	H I	3100' x 250'	10
	I	- 1	
	J	**	
2	A	3100' x 260'	16
3	A	4000' x 200'	5
	B C	1500' x 320'	7
	c	1050' x 920'	Not Operational
	D	5100' x 200'	14
4	A	3250' x 300'	12
	B C	2000' x 550'	6
5	A	920' x 270'	3
	В	2700' x 150'	11
	C	785' x 385'	6
 6	A	-	1
	В	-	
	B C D E	-	
	D	-	1
	E	-	1
	F	-	
7	A	-	
	В	01501 1001	4
	C	2150' x 100'	"
	D	<u>-</u>	

^{*}Choke Point to Choke Point
-Denote Rail-Served Industries

|--|

25X1

A 173 (7), WA 2010 W	
SECRET	25X ⁻

TABLE II
COUNT OF ROLLING STOCK BY FACILITY TIEN-CHING (TIENTSIN), CHINA

25X1

					1			
	RAIL FACILITY	YARD	OPEN CARS	FREIGHT CARS	TANK CARS	PASSENGER CARS	LOCOMOTIVES	
		ŀ						
	1	A	19	5	-	12	8	
		В	-	11	-	-	14 3 2	
		C	-	40	-	20	3	
		D	20	22 4	-	-	2	
j		E	- 8	4	- :	7 7	-	l
		F		11 64 80	-	-	1	
		G	271	64	-	21	-	ļ į
		H	-	80	-	-	1	1 1
		I	18	-	-	-	-	
		J	16	_	2	_	-	_
	2	A	45	97	12	-	2	
	3	A	-	-	-	-	-	
		В	-	-	-	-	-	
		C	- 0)	- -	-	-	-	
		D	284	130	25	-	1	
		E	-	-	-	-	_	
	4	A	99	30	-	-	1	
		В	33 16	-	-	-	-	
		С	16	1	-	-		
	5	A	48	5 82	-	-	•	
		В	52		11	-	1	
		C	1	_		-		
	6	A	1	-	16	-	-	1
		В	-	30	-	-	-	
		C	2	-	-	-	-	
		D		20	-	-	-	
		E	35	-	21	-		
		F	-	-	-		-	
i	7	A	. 6	-	-	-	-	
		В		<u>-</u>	-	<u>-</u>	-	
1		C	24	19	5	1	-	
		D	11	29	4	_	1	
·	TOTAL	•	1009	68o	96	131	35	

SECRET

25X

RAIL FACILITIES IN TIENTSIN, CHINA LOCOMOTIVE REPAIR BUILDINGS

SECRET

Coal-yard General outline of facility 6 service tracks 6 service tracks 95 Turntáble Main repair buildings buildings

25X1

C1A/PID/IB- P-642/63

SECRET

ENCLOSURE NO. 2

25

25

25X

Next 1 Page(s) In Document Exempt